

5 STEPS TO MINIMIZE DAMAGED GRAIN LOSSES

Damaged grain can lead to significant financial losses — but with proper precautions, the risk can be reduced. Here are five key steps to prevent spoilage and maintain grain quality:

1

HARVEST AT THE RIGHT MOISTURE

Harvest grain at the recommended moisture content and dry it properly before storage.

2

USE GENTLE HANDLING PRACTICES

Slow down handling equipment to minimize kernel breakage.

3

MAINTAIN PROPER STORAGE CONDITIONS

Keep bins clean, sealed, and well-aerated to prevent mold and pests.

4

IMPLEMENT A MONITORING ROUTINE

Regularly check grain for signs of spoilage, such as odors or hot spots.

5

PLAN PREVENTATIVE MAINTENANCE

Service and calibrate equipment prior to harvest to ensure efficient operation.



24/7 EMERGENCY LINE:

319-446-7600